



**Western
Bay of Plenty**
District Council



**Eastern
Comprehensive
Stormwater Consent**

Annual Report

November 2022



Table of Contents

1. Introduction	3
2. Purpose of this report	3
3. Monitoring.....	4
4. Infrastructure upgrade works.....	4
5. Erosion, flood risk alleviation, and stormwater quality mitigation measures.....	4
6. Pukehina outlet pipes.....	4
7. Stormwater related incidents.....	5
8. Updated Asset Register.....	5
9. New structures to be included in the consent (asset register)	5
Appendix 1: Plan showing infrastructure upgrades.....	6

1. Introduction

In July 2020, Bay of Plenty Regional Council (BOPRC) granted Western Bay of Plenty District Council (WBOPDC) six new consents relating to Eastern Comprehensive Stormwater Consent:

- Consent 67481-BC.16 River Structure
- Consent 67481-BC.17 Beds Damming and Diversion
- Consent 67481-CC.01 Coastal Dredging
- Consent 67481-CC.02 Occupy Coastal Space
- Consent 67481-DC.05 Discharge to Water
- Consent 67481-LC.05 Earthworks or Excavation

This report examines conditions required for Consent 67481-DC.05 Discharge to Water, which expires 31 May 2055.

2. Purpose of this report

Condition 9.5 of consent 67481-DC.05 requires the consent holder to submit an annual report to BOPRC in November of each year covering:

- a) A summary report of any monitoring undertaken including an analysis of the monitoring results;
- b) Any stormwater network or stormwater infrastructure upgrade works undertaken;
- c) Any stormwater induced erosion, flood risk alleviation, or stormwater quality mitigation measures implemented;
- d) Any incidents resulting in unanticipated contaminants entering the stormwater network, the investigation of the cause of the incidents and any remedial actions implemented to avoid a repeat occurrence of the incident;
- e) An updated Asset Register; and
- f) Any new structures to be included in the consent (Asset Register).

This report covers the period from 1 November 2021 to 31 October 2022.

3. Monitoring

No monitoring has been undertaken during this reporting period.

A Monitoring Plan is currently being developed as per section 7.3(e), and will be forwarded to BOPRC for certification prior to implementation (section 7.6).

4. Infrastructure upgrade works

During this reporting period, the main pipes on Dunlop Road were upgraded, and a new stormwater pond was also built on Dunlop Road.

The site plan showing the upgrades is attached as Appendix 1.

5. Erosion, flood risk alleviation, and stormwater quality mitigation measures

No stormwater induced erosion, flood risk alleviation, or stormwater quality mitigation measures have been implemented during this reporting period.

6. Pukehina outlet pipes

Field sheets prepared by BOPRC drew attention to outlets in Pukehina which required repair. These lines are inspected six-monthly, and no issues have been identified by our contractor to date, other than the occasional need to clean sand out. WBOPDC's network engineer will also visit the site at the next opportunity to assess the condition of these outlets.

7. Stormwater related incidents

The following stormwater related incidents occurred during the reporting period:

Date	Incident	Location	Cause of incident	Any remedial actions to avoid repeat occurrence
18/11/2021	Sewer overflow to stream	Norm Freeman Drive, Te Puke	Fat blockage	Continuing to monitor the situation, as overflows are rare in this area.
13/08/2022	Sewer overflow to stormwater stream	Queen Street, Te Puke	Rags	This sewer line is due to be replaced in the coming months.

8. Updated Asset Register

The asset register is available on request.

9. New structures to be included in the consent (asset register)

The new infrastructure discussed in section 4 above (pipes and pond) are to be added to the asset register upon practical completion.